## **Department of Education**

**Junior Certificate Examinations** 

2002

**Materials and Technology** 

Metalwork

Higher Level

**Marking Scheme** 

Ques	ction 1 - Section A 20 marks Only five parts	to be cour	<u>ted</u>
(a)	Karl Benz - first practical car / also engine Henry Ford - pioneer of mass production / Model T/(Tract Isaac Singer - lock-stitch sewing machine	or -2 marks)	4 marks
(b)	Piston - to rotate the crankshaft		
( )	Name and purpose	(2 + 2)	4 marks
(c)	Aluminium / aluminium alloy / cast iron Good sliding / wearing / dissipates heat	(2 + 2)	4 marks
(d)	To connect the piston to the crankshaft / converts motion Acts as link (Naming Connecting Rod - 2 marks)		4 marks
(e)	Inlet valve: Exhaust valve / Inlet: outlet	(2 + 2)	4 marks
(f)	Thermoplastic - a plastic that softens when heated, (named Insulator - a material that is a poor conductor of heat / electrony - a combination / mixture / of a metal with		C)
	another metal /element (Any two)	(2 + 2)	4 marks
(g)	Identify and name four components - 1=Variable resistor / 2=Light Dependent Resistor / LDR, 3 = Light Emitting Did 4= Transistor. (No identification - no marks)	•	4 marks
Ques	tion 1 - Section B 20 marks Only five parts	to be cour	ited
(a)	Correct circuit diagram with correct symbols - battery, switch, motor, - $(3 \text{ symbols} = 3 / \text{circuit} = 1)$		4 marks

Ques	tion 1 - Section B 20 marks Only five par	ts to be cou	nted
(a)	Correct circuit diagram with correct symbols - battery, switch, motor, - (3 symbols = 3 / circuit = 1)		4 marks
(b)	Two correct steps - drill hole 4.2, tapping size hole, smause tap-wrench and M5 tap (Drill & tap 1+1)	ller hole, (2 + 2)	4 marks
(c)	Sketch of suitable design of steering mechanism Description of how it could be made	(2 + 2)	4 marks
(d)	Mark out, drill holes, file, etc. (3 parts - 4 marks, 2 parts -2 marks)	(2 + 2)	4 marks
(e)	<ul> <li>(i) Sketch showing six surfaces/ general shape</li> <li>(ii) Using folding bars/ vice</li> </ul>	(2 marks) (2 marks)	4 marks
(f)	Alternative drive system named - gear / chain		4 marks

Ques	tion 2 - 20 marks
(a)	Any <i>two</i> important points /How to get information, books, sho

(a)	Any t	<b>wo</b> important points /How to get information, books, (One point - 2 marks)	shops etc	3 marks
(b)	Any t	wo important points / Stages in making, what to do f (One point - 2 marks)	irst, necessary t	ools 3 marks
(c)	(i)	Elevation correct	2 marks	o marky
		Two improvements - support, holes for fixing etc	$(2 \times 2)$	6 marks
	(ii)	Two explanations	$(2 \times 2)$	4 marks
	(iii)	Dipcoating / galvanising / plating - suggested (painting - 2 marks)		4 marks
Ques	tion 3	20 marks		
(a)	Name	e and explain of A, B, C and D		4 marks
(b)	(i)	X = Countersunk / purpose (1+1) Y = Counterbored / purpose (1+1)	(2 + 2)	4 marks
,	(ii)	Drill small hole - use countersunk or large drill	(2 + 2)	4 marks
(c)		ect substitution in formula, correct answer ver 2000RPM - (If correct answer only -4 marks)	(2+2)	4 marks
(d)	Sketc	ch with description (1 for description / 1 for sketch)	(2+2)	4 marks
Ques	tion 4	20 marks		
(a)	Elect	ric Arc furnace		1 mark
(b)	Elect	rodes up - lid off - charge placed		2 marks
(c)	Scrap	steel, some molten iron, lime		3 marks
(d)	Furna	ace is tilted and steel poured		2 marks
(e)	Rolle	ers to allow the furnace to tilt		2 marks
<b>(f)</b>	Melte	ed by the heat from electrodes		2 marks
(g)	Four	alloys named - four properties		8 marks

Ques	stion 5	20 marks		
(a)		Mention method of forming vacuum forming / injection moulding/ blow moulding		
(b)		ole material - Aluminium, Bronze, (2 marks) Two properties (2 x 2)		6 marks
(c)	(i) (ii)	X = 10mm, $Y = Thread angle / 60^{\circ}$	(2 x 3)	6 marks
(d)	Any t	wo actual effects	(2 x 2)	4 marks
Ques	stion 6	20 marks		
(a)	(i) (ii)	High Carbon Steel (HCS) / Tool Steel / Silv Annealing	er steel	2 marks 2 marks
	(iii)	Hardened - heated to red/ loses magnetism, (Heated+quenched 2 marks)	quenched (3 n	narks)
		Tempered -heated to colour, quenched (3 ma (Heated+quenched given again 1 mark)		narks)
		(Trouted questioned given again I mark)		6 marks
	(iv)	Any two - Wear goggles, gloves, protective use air extractor, care in lighting torch / forg	•	2 marks
(b)	Two d	escriptions	$(2 \times 3)$	6 marks
(c)	More	accurate / can measure to 0.02mm		2 marks
Que	stion 7	20 marks		
(a)	Any <i>three</i> parts correctly named A - Lamp, B - Control panel, C - Emergency stop, D - Cutting tool.  (Three names correct - 3 marks, Three descriptions - 3 marks)		6 marks	
(b)	(i)	Two advantages of CNC machines	41	4 marks
	(ii)	Function of stepper motor - to move cutting according to the program	WOI	4 marks
(c)	CAM - Computer Aided Manufacture, CNC - Computer Numerical Control, RAM - Random Access Memory, WWW - World Wide Web 4 marks			4 marks
(d)	Any two correct advantages 2 ma			2 marks