State Examinations Commission

Junior Certificate Examinations

2003

Materials and Technology

Metalwork

Higher Level

Marking Scheme

Ques	stion 1 - Section A	20 marks	Only five parts	to be cour	<u>nted</u>				
(a)	Thomas Edison - in Charles Parsons - ir John Logie Baird -	vented light bul vented first pra invented televis	b / phonograph / gramo ctical steam turbine ion seeing by wireless	phone	4 marks				
(b)	Spark plug - to igni Name and purpose	te / light the fue	1	(2+2)	4 marks				
(c)	(i) Petrol/alcoh(ii) To connect /	ol/LPG/other ga / join the piston	ases to the connecting rod	(2 + 2)	4 marks				
(d)	Part C rotates when the piston moves up and down/ turns								
(e)	 (i) To help cool the engine / air moving past the fins -cools them (ii) Lawnmower/ strimmer/ chainsaw / go kart / con saw etc 								
(f) (g)	Thermosetting - a plastic that does not soften when heated Pilot hole - a small hole drilled to guide a bigger drill (Diagram +label OF Ferrous metal - any metal or alloy that contains iron (<i>Any two</i>) $(2 + 2)$ Identify and name four components - 1=resistor								
(8)	2=Transistor, $3 =$ La	amp / bulb, 4=	switch. (No identification	on - no marks)	4 marks				
Ques	Question 1 - Section B 20 marks <u>Only five parts to be counted</u>								
(a)	Correct circuit diago battery, switch, mo	ram with correct tor, - (3 symbols	t symbols - s = 3 / circuit = 1)		4 marks				
(b)	Two stages describe how drilled (terms of	ed - how faced o only - 2marks)	off, how tapered, how co	entre drilled, $(2+2)$	4 marks				
(c)	Sketch of suitable design of undercarriage (very good sketch - 2 marks average sketch - 1 mark) Description of main components - 2 marks (If named only 1 mark)								
(d)	Mark out, heat on st $(3 \ steps = 4 \ marks, 2)$	trip heater / bend 2 steps = 2 mark	der - bend to angle, ks, 1step =1 mark)		4 marks				
(e)	(i) Sketch show(ii) drill holes an	ving 3 surfaces/ nd use screws a	general shape (<i>Rectang</i>) nd nuts $(1+1=2)$	le 1 mark) (2 n	arks) 4 marks				
(f)	Undercarriage - sup /take off/ land	ports / allows ai	rcraft to stand / move o	on ground					
	Tail Fin - Helps airc	or craft to maintain	stability/keeps in a str	aight path	4 marks				

a)	Any two important points / strength - weight / corrosion properties/cost							
1 \		(One point - 2 marks)	3 marks					
b)	Any t	<i>wo</i> important points / information for making, dimensions, differer	a marks					
c)	 (i) Elevation: correct shape of body, wheels in correct position, draw bar shown proportion good 							
	(4 coi	(4 correct - 6 marks, 3 correct - 4 marks, 2 correct - 3 marks, 1 correct - 2 marks)						
			6 marks					
	(ii)	Two improvements: handle for end of draw bar, sides on body,						
		bigger wheels, brakes etc (2×2)	4 marks					
	(iii)	Mechanism described: fulcrum for steering / may be text	4 marks					
)ues	tion 3	20 marks						
a)	So that different sizes of holes /different processes may be drilled at correct cutting							
/	speed	s. So that different materials may be drilled eg soft and hard $(2 +$	2) 4 marks					
b)	(i)	Two good appropriate steps $(2+2)$	4 marks					
	(ii)	Secure workpiece in machine vice on drill table, position						
		for first hole - lock vice to table -Use pilot hole/ Jig,						
		Drill 18mm hole - Morse taper drill (Any four)	4 marks					
c)	Corre	ct substitution in formula, correct answer $(2+2)$						
	Answ	er 1000RPM - (If correct answer only - 4 marks)	4 marks					
d)	Sketc	h with description - Depth gauge and taper tap						
,	(1 for	description / 1 for sketch: for each one) $(2+2)$	4 marks					
)ues	tion 4	20 marks						
a)	Blast	furnace	1 mark					
L)	Diain		1 mark					
0)	rig ii	011	I Mark					
c)	Iron c	ore, coke and limestone	3 marks					
d)	Purpose of Part A is to supply air							
	(i)	Maltan nig iron is removed at P	2 marks					
9	(1) (i)	Slag is removed at C (If A and B mixed up 2 marks only)	2 marks					
	(1)	Stag is temoved at C (1) A unu B mixed up - 2 marks only)	2 111 a 1 K5					
f)	The c	The charge is heated by the burning of the coke with air blasts						
~)	(i)	Aluminium, copper, tin, lead, zinc etc	3 marks					
g)	. ,							

Question 520 marks(a)Suitable material named with reason (1+1 = 2 for material + reason))Part A - handlebars; steel, stainless steel, aluminium alloy									
	Part	B - tyre; rubber Part C - mudguard - sheet metal /	plastic	6 marks					
(b)	(i) (ii)	2 marks 2 marks							
(c)	Sketc Good Poor	6 marks							
	1 001	skelen deans net elear awara up to 5 marks		0 mar K5					
(d)	Any t inspe	4 marks							
Que	stion 6	20 marks							
(a)	(i)	Two steps: cleaning, fluxing, heating /protect com	ponent,						
	$(\cdot \cdot)$	clamping / holding / applying solder	(2×2)	4 marks					
	(11)	I in and lead	(1+1)	2 marks					
	(iii)	(iii) Purpose of flux: to prevent oxidation / keep joint clean							
	(iv)	(iv) Any three - Wear goggles, gloves, protective clothing, care with hot bit, care with lit torch, use air extractor, care in lighting torch not to spill flux use low voltage bit $(3x1)$ 3 marks							
(b)	Two p solidi	4 marks							
(c)	Any t Clear Engra	Any two: Alloy - combination / mixture of metals, Clearance angle -angle on cutting tool, allows cutting edge to cut Engraving - decorating metal using sharp tool / engraving machine4 marks							
Question 7 20 marks									
(a)	Input	mouse, digital camera, modem, scanner							
	Outpu	it: CNC machine, printer, modem	(6 x 1)	6 marks					
(b)	 Function of any four: Mouse- digital input pointer, camera - inputs digital images, modem - email / Internet, scanner- images, 								
	mode	m - receives information email etc		4 marks					
()			1						
(C)	DOS - disk operating system, Computer virus - bug that damages corrupts 4 marks								
(d)	Any t v	vo correct advantages (2×2)		4 marks					
(f) Any two : Test run - simulated on screen, define a profile -inputting X and Z data, Canned cycle - part cycle already stored, program - list of commands									
				2 marks					