

GAUTENG DEPARTMENT OF EDUCATION
SENIOR CERTIFICATE EXAMINATION

FITTING AND TURNING SG

OCTOBER / NOVEMBER 2005
OKTOBER / NOVEMBER 2005

TIME: 3 hours

MARKS: 200

REQUIREMENTS:

- Pocket calculator and drawing instruments

INSTRUCTIONS:

- Answer ALL the questions.
 - Unless otherwise indicated, all dimensions are in millimetres.
 - For ALL applicable questions, the dividing head ratio is 40:1 and the milling machine lead screw pitch is 6 mm.
 - An information sheet appears on pages 8 to 10 of this question paper.
 - Use ONLY the formulae indicated on the information sheet. Derivatives of these formulae may however also be used.
-
-

QUESTION 1

Answer Question 1.1 to 1.8 on the **answer sheet** on the **inside cover** of the **answer book**. For each question, indicate the correct answer(s) by making a cross (X) over the appropriate letter(s) on the answer sheet. The mark allocation on the right-hand side is an indication of the number of correct answers for each question. There may be more than one correct answer.

1.1 The working depth of a gear refers to _____.

- A. the depth at which the gears mesh properly
- B. the addendum
- C. the dedendum
- D. two times the addendum

(2)

1.2 The involute shape of gear teeth is the most commonly used shape of gear teeth. This shape is preferred for the following reasons:

- A. It is cheaper than other shapes.
- B. They are stronger at the root.
- C. It does not easily wear off.
- D. They are easy to machine.

(2)

- 1.3 The function of a milling machine tailstock is to support the workpiece _____.
- A. and clamp it during machining
 - B. while tapers are being machined
 - C. when cutting splines
 - D. when cutting helical gears
- (2)
- 1.4 The arbor on a milling machine is employed when _____.
- A. large flat surfaces must be machined
 - B. we use side and face cutters
 - C. the machine cross travel is too small
 - D. the machine has limited power
- (2)
- 1.5 Absolute programming is when _____.
- A. all dimensions are the same
 - B. we take all dimensions from one point
 - C. we refer to a common reference point
 - D. all dimensions are different
- (2)
- 1.6 A dividing head on a milling machine is used _____.
- A. to determine the angle between two plates on a workpiece
 - B. when gear racks are machined
 - C. to set up toolmakers' buttons
 - D. to divide the circumference of a workpiece into a number of equal divisions
- (2)
- 1.7 Accidents in a workshop occur as a result of personal or work-related factors. Which of the following are personal factors?
- A. Very little or no knowledge/skills
 - B. Bad electrical connections
 - C. Bad attitudes
 - D. Holes in workshop floors
- (2)
- 1.8 One button in a set of toolmakers' buttons is always longer than the others. The reason is that _____.
- A. the shorter buttons are sometimes too short for accurate spacing
 - B. it is always machined more accurately than shorter ones
 - C. it helps when the holes are closely spaced
 - D. None of the above.
- (1)

Answer Questions 1.9 to 1.13 in your **answer book**. Write only TRUE or FALSE next to the appropriate question number.

- 1.9 The sector arms on a dividing head are used only for rapid indexing.
- 1.10 Single helical gears cause end thrust on machine bearings.
- 1.11 Friction is a definite disadvantage when we consider machine bearings.
- 1.12 When a fluid in a container is placed under pressure, its volume will decrease.
- 1.13 Undercutting at the start of a screw thread is done to increase the strength of the screw thread.

5x2=(10)
[25]

QUESTION 2

- 2.1 Briefly discuss the aspects **accessibility** and **visibility** with regard to measures for a good workshop layout. (8)
- 2.2 Mention FIVE **aims** of preventative maintenance. (5)
- 2.3 Draw the dividing head and lead screw gear arrangement when a gear rack must be machined on a milling machine. (6)
- 2.4 A helical gear with a real module of 5,32 mm and a helix angle of 20° must be cut on a milling machine. The pitch circle diameter of the gear is 212,8 mm. Calculate the following, indicating all calculations:
 - 2.4.1 Normal module of the gear
 - 2.4.2 Number of teeth of the gear
 - 2.4.3 Number of teeth marked on the cutter
 - 2.4.4 Cutting depth of the gear
 - 2.4.5 Outside diameter of the gear (14)
- 2.5 Calculate the chordal width of a spur gear with 60 teeth and a module of 5 mm. (2)


[35]

QUESTION 3


3.1 Twelve holes must be drilled on a PCD of 267,2 mm on a centre lathe. Toolmakers' buttons with a diameter of 15 mm are used for the set up. Calculate the following:

3.1.1 Centre distance between holes 1 and 5.

3.1.2 Distance between buttons 1 and 9. (10)



3.2 The simple line diagram below shows two arms of a cranked lever, completely out of balance. Draw up a mass/distance table and determine graphically the distance from the hub at which a 7 kg mass must be fitted in order to balance the lever. Determine the angle between the balance mass and the 3 kg arm. Use a scale of 1 cm = 40 kg.mm. (11)




- 3.3 Draw neat sketches to illustrate each of the following:
- 3.3.1 Static balancing using two unequal mass pieces (4)
- 3.3.2 Incremental programming with reference to numerically controlled lathes (5)
- 3.4 State FIVE methods that may be used to test the accuracy of external tapers. (5)
- [35]**

QUESTION 4

- 4.1 A two-start external square thread must be cut on a centre lathe. The lead of the thread is 30 mm and the outside diameter is 75 mm. The clearance angle is 4° . Calculate the following details of the screw thread and show all your calculations:
- 4.1.1 Helix angle
- 4.1.2 Leading angle
- 4.1.3 Following angle (11)
- 4.2 Explain in detail how the screw thread described in Question 4.1 should be cut using the “change gear” method. (10)
- 4.3 Give a brief description of “up-cut” milling under the following headings:
- 4.3.1 A sketch to show what up-cut milling is
- 4.3.2 THREE advantages of up-cut milling
- 4.3.3 TWO disadvantages of up-cut milling (8)
- 4.4 Mention SIX reasons why milling cutters fail. (6)
- [35]**

QUESTION 5

- 5.1 The dovetail in the sketch below is being tested for accuracy using two precision rollers. The dimension in the neck of the dovetail is 55,772 mm and the rollers have a diameter of 20 mm. The included angle of the dovetail is 60° , as indicated. Calculate the distance between the two rollers and show all calculations. (16)



- 5.2 The liquid pressure in a 360 mm diameter cylinder is 4 MPa. Calculate the force exerted when the piston moves outward and show your calculations. (7)
- 5.3 Calculate the diameter of a strut used to support a load of 25 000 kg. The stress in the strut is 200 MPa. Show all calculations. (8)
- 5.4 Name the FOUR laws of **sliding friction**. (4)
- [35]**

QUESTION 6

- 6.1 When a force of 100 N is exerted on the plunger of a hydraulic press, the plunger will move 90 mm downward. Calculate the following and show your calculations:
- 6.1.1 Distance the ram will move upward if the area of the plunger is 0,2 m² and the area of the ram is 1,8 m²
- 6.1.2 Force that will be exerted by the ram (8)
- 6.2 You are required to sharpen the teeth of a 180 mm diameter side and face milling cutter on a tool and cutter grinder. The teeth have a primary clearance angle of 7° and a 200 mm diameter cup grinding wheel is used for the job.
- 6.2.1 Draw a sketch of the set-up to illustrate the position of the tooth rest of the tool and cutter grinder. (6)
- 6.2.2 Calculate the off-set of the tooth rest and show your calculations. (3)
- 6.3 A gear blank must be divided into 103 divisions using a milling machine dividing head with a ratio of 40:1. Choose 100 divisions (for the differential indexing) and calculate the following:
- 6.3.1 Required indexing
- 6.3.2 Change gears needed
- 6.3.3 Direction of rotation of the index crank (10)
- 6.4 State FIVE examples in practice when friction is applied as an advantage. (5)
- 6.5 Draw a neat, cross-sectional sketch of a toolmaker's button in position on a plate. (3)
- [35]**

TOTAL: 200

INFORMATION SHEET

1. Gears for milling machine

Standard and special gear wheels.

24 (two of); 28; 32; 40; 44; 46; 47; 48; 52; 56; 58; 64; 68; 70; 72; 76; 84; 86 and 100 teeth.

2. Index plate for milling machine

24; 25; 28; 30; 34; 37; 38; 39; 41; 42; 43; 46; 47; 49; 51; 53; 54; 57; 58; 59; 62 and 66 holes.

3. Formulae

$$3.1 \quad \text{Stress} = \frac{F}{A}$$

$$3.2 \quad \text{Cross-sectional area of solid cylinder} = \frac{\pi D^2}{4}$$

$$3.3 \quad \text{Cross-sectional area of hollow cylinder} = \frac{\pi(D^2 - d^2)}{4}$$

$$3.4 \quad \text{Fluid pressure in a hydraulic press:} \quad \frac{F1}{A1} = \frac{F2}{A2}$$

$$\begin{aligned} \text{Volume of fluid displaced by plunger} &= \text{volume displaced by piston} \\ \text{volume} &= \text{area} \times L \end{aligned}$$

3.5 Spur gears:

$$3.5.1 \quad \text{PCD} = Tm$$

$$3.5.2 \quad \text{add} = m$$

$$3.5.3 \quad \text{ded} = 1,157_m$$

$$3.5.4 \quad \text{Clearance} = 0,157_m$$

$$3.5.5 \quad \text{OD} = \text{PCD} + 2 \text{ add}$$

$$3.5.6 \quad T = \frac{\text{PCD}}{m}$$

$$3.5.7 \text{ Chordal addendum} = m + \left[\frac{mT}{2} \left(1 - \cos \frac{90^\circ}{T} \right) \right]$$

$$3.5.8 \text{ Chordal width} = mT \sin \frac{90^\circ}{T}$$

$$3.5.9 \text{ Circular pitch} = \pi m$$

3.6 Helical gears

$$3.6.1 \text{ PCD} = TM_w$$

$$3.6.2 \text{ add} = m_n$$

$$3.6.3 \text{ ded} = 1,157 m_n$$

$$3.6.4 \text{ clearance} = 0,157 m_n$$

$$3.6.5 \text{ OD} = \text{PCD} + 2 \text{ add}$$

$$3.6.6 \text{ T} = \frac{PCD}{m_c}$$

$$3.6.7 m_n = m_c \cos \theta$$

3.6.8 Number of teeth marked on the milling cutter;

$$\text{Number} = \frac{T}{(\cos \theta)^3}$$

$$3.6.9 \text{ Chordal addendum} = m_n + \left[\frac{m_n T}{2} \left(1 - \cos \frac{90^\circ}{T} \right) \right]$$

$$3.6.10 \text{ Chordal thickness} = m_n T \sin \frac{90^\circ}{T}$$

$$3.6.11 \text{ Lead of helix} : l = \pi \times \text{PCD} \times \cot \theta$$

or

$$l = \frac{\pi \times \text{PCD}}{\tan \theta}$$

$$3.6.12 \text{ Helix angle} : \tan \theta = \frac{\pi \times \text{PCD}}{l}$$

$$3.6.13 \text{ Circular pitch} = \pi m_n$$

3.6.14 Lead of milling machine = Dividing head ratio x pitch of leadscrew

$$3.6.15 \text{ Change gears required} \quad \frac{Dr}{G} = \frac{L}{l}$$

3.7 Indexing:

$$3.7.1 \text{ Simple indexing} = \frac{40}{N}$$

$$3.7.2 \text{ Angular indexing} = \frac{\theta}{90^\circ}$$

$$3.7.3 \text{ Differential indexing} = \frac{Dr}{G} = \frac{(A-N)}{A} \times \frac{40}{1}$$

3.7.4 Rack:

$$\text{Indexing} = \frac{\text{Dividing head ratio}}{\text{Pitch of lead screw}} \times \frac{\text{Pitch of rack}}{\text{Gear ratio}}$$

3.8 Grinding of milling cutter teeth:

3.8.1 Regular disc grinding wheel: Offset = R sin θ .3.8.2 Cup grinding wheel: Offset = r sin θ .

3.9 Graphical solution of static balancing:

Out-of-balance effect = Mass x distance of mass from centre of face plate.

3.10 Tool angles for cutting square threads:

$$3.10.1 \text{ Helix angle: } \tan \eta = \frac{\text{Lead}}{\pi D_m}$$

$$3.10.2 \text{ Leading tool angle} = 90^\circ - (\text{Helix angle} + \text{Clearance angle})$$

$$3.10.3 \text{ Following tool angle} = 90^\circ + (\text{Helix angle} - \text{Clearance angle})$$