

GAUTENG DEPARTMENT OF EDUCATION  
SENIOR CERTIFICATE EXAMINATION

FITTING AND TURNING SG

FEB / MAR 2006

TIME: 3 hours

MARKS: 200

---

---

**REQUIREMENTS:**

- Pocket calculator and drawing instruments

**INSTRUCTIONS:**

- Answer ALL the questions.
  - Unless otherwise indicated, all dimensions are in millimetres.
  - For ALL applicable questions, the dividing head ratio is 40:1 and the milling machine lead screw pitch is 6 mm.
  - An information sheet appears on pages 8 to 10 of this question paper.
  - Use ONLY the formulae indicated on the information sheet. Derivatives of these formulae may however also be used.
  - Show all calculations to earn part of the marks for them.
- 
- 

**QUESTION 1**

Answer Questions 1.1 to 1.9 on the **answer sheet** on the **inside cover** of the **answer book**. For each question, indicate the correct answer(s) by making a cross (X) over the appropriate letter(s) on the answer sheet. The mark allocation on the right-hand side is an indication of the number of correct answers for each question. There may be more than one correct answer.

- 1.1 The purpose of maintenance is to \_\_\_\_\_.
- A. prevent workers from working overtime
  - B. minimise replacement costs
  - C. improve the quality of equipment
  - D. keep workers on their toes
- (2)
- 1.2 The advantages of multiple start screw-threads over single start screw-threads are that \_\_\_\_\_.
- A. larger diameter shafts may be used
  - B. smaller pitches can be cut
  - C. shallower threads, thus stronger thread cores, are obtained
  - D. faster axial movement is obtained
- (2)

- 1.3 Points of-action guards are used on \_\_\_\_\_.
- A. guillotines
  - B. rotating shaft ends
  - C. gearboxes
  - D. circular saws
- (2)
- 1.4 Form milling has its advantages and disadvantages. Identify the disadvantages from the list below.
- A. Large cutter diameters needed
  - B. Unsuitable for other work
  - C. Must cut at high speed
  - D. Expensive
- (2)
- 1.5 Single helical gears have advantages and disadvantages. Choose the disadvantages from the list below.
- A. Power distribution over two teeth
  - B. Causes end thrust
  - C. Frictionless movement
  - D. Noisy
- (1)
- 1.6 Gear tooth verniers measure the \_\_\_\_\_ of a gear.
- A. addendum
  - B. dedendum
  - C. work depth
  - D. chordal width
- (1)
- 1.7 The factors that will influence the magnitude of the helix angle of a screw-thread are the \_\_\_\_\_.
- A. lead of the thread
  - B. primary clearance angle of the cutting tool
  - C. root diameter of the thread
  - D. outside diameter of the thread
- (2)
- 1.8 Rapid indexing means that \_\_\_\_\_.
- A. there is no need for calculations
  - B. the lead screw must be disengaged
  - C. the lead screw must be coupled to the dividing head
  - D. indexing is simple and fast
- (2)

- 1.9 Rivets are used for the joints in a large pressure vessel. To which of the following types of stress will the rivets be subjected?
- A. Tensile stress
  - B. Shear stress
  - C. Compressive stress
  - D. A combination of tensile and compressive stress
- (1)

Answer Questions 1.10 to 1.14 in **your answer book**. You are required to write only TRUE or FALSE next to the appropriate question number.

- 1.10 Undercutting at the end of a screw-thread is done to accommodate the cutting tool. (2)
- 1.11 The purpose of the secondary clearance angle on a milling cutter is to provide space for the cuttings and to permit the coolant to flow away. (2)
- 1.12 The amount of frictional resistance between two sliding surfaces depends on the magnitude of the force which keeps the surfaces in contact with each other. (2)
- 1.13 Left-hand screw-threads are only used on wheels that rotate anticlockwise. (2)
- 1.14 For dynamic balancing, the centres of gravity of all the masses in a system must be in the same plane. (2)
- [25]**

### QUESTION 2

- 2.1 Mention the FIVE components of good workshop administration. (5)
- 2.2 Name FOUR aspects of preventative maintenance. (4)
- 2.3 Mention FOUR advantages of a good workshop layout. (4)
- 2.4 Draw a neat, labelled sketch of the dividing-head gear arrangement for when differential indexing must be performed. (6)
- 2.5 A spur gear has 75 teeth and a module of 6 mm. Calculate the following particulars of the gear:
- 2.5.1 Pitch circle diameter
  - 2.5.2 Outside diameter
  - 2.5.3 Dedendum
  - 2.5.4 Addendum
  - 2.5.5 Work depth
  - 2.5.6 Full depth
- (12)
- 2.6 Calculate the chordal addendum of a helical gear with 56 teeth and a normal module of 4,8 mm. The helix angle of the gear is 20°. (4)


**[35]**

**QUESTION 3**

3.1 Five holes must be drilled on a pitch circle as indicated on the sketch. Toolmakers' buttons with a diameter of 10 mm are used for the set up. The distance between buttons 1 and 2 is 85 mm. Calculate the


- 3.1.1 chordal distance of holes 1 and 2.
- 3.1.2 pitch circle diameter of the holes.
- 3.1.3 distance between buttons 1 and 4.

(12)



3.2 The diagram below represents two unbalanced arms of a machine part. Determine graphically the angle ? and the magnitude of the balance mass (in kg) placed at a distance of 75 mm from the centre of the hub to balance the part. Draw up a mass/distance table to indicate the units you are going to use for your vector diagram. Use a scale of 1 mm = 20 kg.mm.

(11)



3.3 By means of a neat line sketch, indicate how a workpiece mounted on a face plate must be statically balanced using two equal mass pieces.

(4)


- 3.4 Name FOUR advantages of using a numerically controlled machine. (4)
- 3.5 Mention FOUR examples in practice where friction is considered a disadvantage. (4)
- [35]**

#### QUESTION 4

- 4.1 A three-start internal V-thread with a root diameter of 35 mm and a pitch of 4 mm must be cut on a pipe with an outside diameter of 50 mm and a wall thickness of 10 mm. Calculate the
- 4.1.1 effective diameter of the thread.
- 4.1.2 lead of the thread.
- 4.1.3 helix angle of the thread.
- 4.1.4 leading angle of the cutting tool.
- 4.1.5 following angle of the cutting tool. (13)
- 4.2 Describe, in detail, how to cut the screw-thread described in Question 4.1 on a lathe using the **compound slide** method. (10)
- 4.3 Mention FIVE advantages of coarse-tooth milling cutters over fine-tooth milling cutters. (5)
- 4.4 Define the term **slab milling**. (2)
- 4.5 Name FIVE reasons why helical milling cutters are sometimes nicked. (5)
- [35]**

#### QUESTION 5

- 5.1 The internal dovetail in the sketch below must be tested for accuracy. The dimensions of the dovetail are as indicated on the sketch. Calculate the dimensions **X** and **W**. (16)



- 5.2 A pressure of 35 MPa is required in the cylinder of a hydraulic jack to lift a load of 12 250 N. Calculate the diameter of the jack piston. (7)
- 5.3 A strut of a steel frame is subjected to a tensile load. The stress induced in the strut is measured at 7,3 MPa just before the strut fractures. The strut is a 25 mm x 50 mm hollow rectangular tube with a 3 mm wall thickness. Calculate the magnitude of the tensile load. (9)

- 5.4 Name THREE detrimental consequences/effects of friction on the moving parts of a machine.

(3)  
[35]

### QUESTION 6

- 6.1 The ram of a hydraulic press can lift a load of 15 kN when a force of 300 N is exerted on the plunger. The diameter of the ram is 565,7 mm. Calculate the

6.1.1 pressure in the press.

6.1.2 diameter of the plunger.

(12)

- 6.2 A 150 mm diameter disc-grinding wheel must be used to sharpen the teeth of a 120 mm diameter side and face cutter. The primary clearance angle is  $4^\circ$ .

6.2.1 Calculate the off-set of the tooth rest.

6.2.2 Draw a sketch to show the position of the tooth rest in relation to the grinding wheel.

(9)

- 6.3 Calculate the indexing in each of the following cases:

6.3.1 An angle of  $13^\circ 20'$

6.3.2 Differential indexing for 119 teeth (Choose 120 teeth). Determine the

(a) necessary indexing.

(b) change gears needed.

(c) rotational direction of the index plate.

(14)  
[35]

**TOTAL: 200**

## INFORMATION SHEET

1. Gears for milling machine

Standard and special gear wheels

24 (two of); 28; 32; 40; 44; 46; 47; 48; 52; 56; 58; 64; 68; 70; 72; 76; 84; 86 and 100 teeth.

2. Index plate for milling machine

24; 25; 28; 30; 34; 37; 38; 39; 41; 42; 43; 46; 47; 49; 51; 53; 54; 57; 58; 59; 62 and 66 holes.

3. Formulae

$$3.1 \quad \text{Stress} = \frac{F}{A}$$

$$3.2 \quad \text{Cross-sectional area of solid cylinder} = \frac{\pi D^2}{4}$$

$$3.3 \quad \text{Cross-sectional area of hollow cylinder} = \frac{\pi(D^2 - d^2)}{4}$$

$$3.4 \quad \text{Fluid pressure in a hydraulic press:} \quad \frac{F1}{A1} = \frac{F2}{A2}$$

$$\begin{aligned} \text{Volume of fluid displaced by plunger} &= \text{volume displaced by piston} \\ \text{volume} &= \text{area} \times L \end{aligned}$$

3.5 Spur gears:

$$3.5.1 \quad \text{PCD} = Tm$$

$$3.5.2 \quad \text{add} = m$$

$$3.5.3 \quad \text{ded} = 1,157_m$$

$$3.5.4 \quad \text{Clearance} = 0,157_m$$

$$3.5.5 \quad \text{OD} = \text{PCD} + 2 \text{ add}$$

$$3.5.6 \quad T = \frac{\text{PCD}}{m}$$

$$3.5.7 \text{ Chordal addendum} = m + \left[ \frac{mT}{2} \left( 1 - \cos \frac{90^\circ}{T} \right) \right]$$

$$3.5.8 \text{ Chordal width} = mT \sin \frac{90^\circ}{T}$$

$$3.5.9 \text{ Circular pitch} = \pi m$$

### 3.6 Helical gears

$$3.6.1 \text{ PCD} = TM_w$$

$$3.6.2 \text{ add} = m_n$$

$$3.6.3 \text{ ded} = 1,157 m_n$$

$$3.6.4 \text{ clearance} = 0,157 m_n$$

$$3.6.5 \text{ OD} = \text{PCD} + 2 \text{ add}$$

$$3.6.6 \text{ T} = \frac{PCD}{m_c}$$

$$3.6.7 m_n = m_c \cos \theta$$

3.6.8 Number of teeth marked on the milling cutter:

$$\text{Number} = \frac{T}{(\cos \theta)^3}$$

$$3.6.9 \text{ Chordal addendum} = m_n + \left[ \frac{m_n T}{2} \left( 1 - \cos \frac{90^\circ}{T} \right) \right]$$

$$3.6.10 \text{ Chordal thickness} = m_n T \sin \frac{90^\circ}{T}$$

$$3.6.11 \text{ Lead of helix} : l = \pi \times \text{PCD} \times \cot \theta$$

or

$$l = \frac{\pi \times \text{PCD}}{\tan \theta}$$

$$3.6.12 \text{ Helix angle} : \tan \theta = \frac{\pi \times \text{PCD}}{l}$$

$$3.6.13 \text{ Circular pitch} = \pi m_n$$

3.6.14 Lead of milling machine = Dividing head ratio x pitch of leadscrew

$$3.6.15 \text{ Change gears required} \quad \frac{Dr}{G} = \frac{L}{l}$$



3.7 Indexing:

3.7.1 Simple indexing =  $\frac{40}{N}$

3.7.2 Angular indexing =  $\frac{?}{90}$

3.7.3 Differential indexing =  $\frac{Dr}{G} = \frac{(A-N)}{A} \times \frac{40}{1}$

3.7.4 Rack:

Indexing =  $\frac{\text{Dividing head ratio}}{\text{Pitch of lead screw}} \times \frac{\text{Pitch of rack}}{\text{Gear ratio}}$

3.8 Grinding of milling cutter teeth:

3.8.1 Disc grinding wheel: Offset =  $R \sin \theta$ .

3.8.2 Cup wheel: Offset =  $r \sin \theta$ .

3.9 Graphical solution of static balancing:

Out-of-balance effect = Mass X distance of mass from centre of face plate.

3.10 Tool angles for cutting square threads:

3.10.1 Helix angle:  $\tan \eta = \frac{\text{Lead}}{pD_m}$

3.10.2 Leading tool angle =  $90^\circ - (\text{Helix angle} + \text{Clearance angle})$

3.10.3 Following tool angle =  $90^\circ + (\text{Helix angle} - \text{Clearance angle})$