

**GAUTENG DEPARTMENT OF EDUCATION
SENIOR CERTIFICATE EXAMINATION**

**METALWORK SG
(Second Paper: Theory)**

POSSIBLE ANSWERS OCT / NOV 2006

QUESTION 1

- | | |
|------|---|
| 1.1 | B |
| 1.2 | B |
| 1.3 | C |
| 1.4 | D |
| 1.5 | B |
| 1.6 | C |
| 1.7 | D |
| 1.8 | B |
| 1.9 | D |
| 1.10 | B |
| 1.11 | C |
| 1.12 | B |
| 1.13 | D |
| 1.14 | C |
| 1.15 | B |
| 1.16 | C |
| 1.17 | D |
| 1.18 | D |
| 1.19 | B |
| 1.20 | D |

[20]

QUESTION 2

- | | | |
|-----|--------|---|
| 2.1 | 2.1.1 | T |
| | 2.1.2 | T |
| | 2.1.3 | F |
| | 2.1.4 | T |
| | 2.1.5 | F |
| | 2.1.6 | T |
| | 2.1.7 | F |
| | 2.1.8 | T |
| | 2.1.9 | F |
| | 2.1.10 | T |

(10)

- | | | |
|-----|-------|---|
| 2.2 | 2.2.1 | Heat to bright red. Restores the malleability of a metal. Cover with sand, ash or lime. |
| | 2.2.2 | Heated to bright red colour, quickly cooled in water or oil. Heat metal with a carbonising flame. |
| | 2.2.3 | Subject metal to heat and place in carbon-rich material. Carbon penetrates surface. |


(2 each) (6)

2.3 To absorb shock without breaking. (1)

2.4 Brown
 Yellow
 Orange
 Red (Cherry)
 Purple (Any 3) (3)
[20]

QUESTION 3

3.1 Centre punch 90° angle Prick punch 60° angle
 Centre punch large Prick punch is smaller
 Centre punch: Boring of holes Prick punch: To make prick punch lines




(3 each) (6)

3.2 3.2.1 Gripping and cutting
 3.2.2 Eyes in wire
 3.2.3 To work through small openings
 3.2.4 Cutting of wire (4)

3.3 3.3.1 V-Block and clamp
 3.3.2 Vice protection plates
 3.3.3 Flat cold chisel
 3.3.4 Tap wrench
 3.3.5 Round-nose chisel
 3.3.6 Dividers
 3.3.7 Triangular file
 3.3.8 Brass pin
 3.3.9 Stillson wrench
 3.3.10 Ball pene hammer (10)
[20]


QUESTION 4

4.1




(5)

4.2




(7)

4.3



(5)

4.4

(3)
[20]**QUESTION 5**

- 5.1
- | | | | |
|----|-------------------|----|------------------------------|
| A. | Chuck | G. | Tailstock spindle lock lever |
| B. | Driving plate | H. | Tailstock |
| C. | Bent-tail carrier | I. | Tailstock hand wheel |
| D. | Live centre | J. | Tailstock lock nut |
| E. | Tailstock sleeve | K. | Tailstock base |
| F. | Tailstock centre | L. | Lathe bed |
- (12)
- 5.2
- Test for cracks
 - Paper washers on both sides of the grinding wheel
 - Aluminium flanges for tightening must be ? of grinding wheel diameter
 - To replace all shields
 - To first turn the wheel by hand to check for balance
 - Adjust the material support
- (6)
- 5.3
- Emery
 - Carborundum
 - Aluminium oxide
 - Silicon carbide
- (Any 2) (2)
[20]

QUESTION 6

- 6.1
- 6.1.1 Red in colour
Soft
1083⁰ melting point
Good conductor of heat and electricity does not rust.
- (4)
- 6.1.2 Can be alloyed
Can be soldered or brazed
Can be drilled or folded
Can be polished
Can be machined
- (Any 4) (4)
- 6.1.3
- | | | | |
|----|-----------------|----|----------|
| a) | Open pit mining | e) | Smelter |
| b) | Crushing | f) | Refining |
| c) | Milling | g) | Casting |
| d) | Flotation | h) | Shaping |
- (8)

6.2	6.2.1	Ductility	
	6.2.2	Fusibility	
	6.2.3	Lustre	
	6.2.4	Hardness	(4)
			[20]


QUESTION 7

7.1	7.1.1	Scrap Cold pig iron Iron oxide Iron ore Alloy elements	(5)
	7.1.2	<ul style="list-style-type: none"> – Remove carbon electrodes – Swing roof away – Charge the furnace – Close roof – Lower carbon electrodes – Strike arc – Tap metal 	(Any 3) (3)
	7.1.3	<ul style="list-style-type: none"> – A pre-determined voltage is maintained – Electrodes gap is small enough to strike an arc – Heat of the arc melts the furnace charge – To prevent over heating of the furnace lining a low tension current is passed through for 15 minutes – Melting process lasts 2 – 2½ hours – Refining – Alloy additions and tapping 	(7)
7.2	D x S = d x s D = Driving Pulley S = rpm driven pulley d = Diameter driven pulley s = rpm chuck of driven pulley		(5) [20]


QUESTION 8

8.1	8.1.1	Thinner than 5 mm	
	8.1.2	Welding rod stay in welded pool to move steadily to the right.	(2)
8.2	8.2.1	Permanent: <ul style="list-style-type: none"> – Gas welding, arc welding – Soldering 	
	8.2.2	Semi-permanent: <ul style="list-style-type: none"> – Rivets and seams 	
	8.2.3	Temporary: <ul style="list-style-type: none"> – Bolts and nuts – Metal screws 	2x3= (6)


8.3 8.3.1 More acetylene
Less oxygen



8.3.2 50% oxygen
50% acetylene



8.3.3 More oxygen
Less acetylene



(9)

8.4 Copper
Silver
Cadmium
Gold
Phosphorus
Zinc

(Any 3) (3)
[20]

QUESTION 9

9.1 9.1.1 – Welding crater
– Under-cutting – overheating electrode
– Burn-through

(Any 2)

9.1.2 – Slag inclusion
– Insufficient penetration
– Blow holes
– Hollow welds

(Any 2)

9.1.3 – Reduced penetration
– Leg length is unequal
– Splatter

9.1.4 – Reduced penetration
– Leg length is unequal
– Rod sticks to metal

(8)

9.2 – Metal core
– Flux coating

(2)

9.3 A process of permanently joining metals using electricity
The heat of the arc melts the parent metal
Parent metal and electrode form a solid mass on cooling

(3)

- 9.4 9.4.1 Arc length too short, low amperage, welding rod too thick (Any 1)
- 9.4.2 Wrong joint preparation
- 9.4.3 Amperage too high, Welding rod too thin
- 9.4.4 Rod too thick, Amperage too low
- 9.4.5 Amperage too high, Rod too thin
- 9.4.6 Too slow welding speed
- 9.4.7 Welding speed too fast (7)
- [20]**

QUESTION 10

- 10.1 – Identification of needs
 – Development of a design proposal
 – Organising and production
 – Evaluating (4)
- 10.2 10.2.1 Ordinary solder
 10.2.2 Fine solder
 10.2.3 Plumber's solder (3)
- 10.3 – Relieve surface tension
 – To make the solder flow
 – To evenly spread the solder
 – Chemically clean the surface (Any 3) (3)
- 10.4 – The iron must be cleaned and tinned
 – The iron must be hot enough
 – Parent metal must be hot enough
 – Joint must be chemically clean
 – Plates must be a perfect fit
 – Correct flux must be used (Any 5) (5)
- 10.5 – Clean the hot bit
 – Point is cleaned in sal-ammoniac block
 – The solder is melted in the sal-ammoniac block
 – Tip is dipped in the molten solder
 – Solder sticks to tip of soldering iron ready to solder. (5)
- [20]**

TOTAL: 200