

Mark Scheme (Results) Summer 2010

Principal Learning

Construction
CB204 Create the Built Environment: Structures



Edexcel is one of the leading examining and awarding bodies in the UK and throughout the world. We provide a wide range of qualifications including academic, vocational, occupational and specific programmes for employers. Through a network of UK and overseas offices, Edexcel's centres receive the support they need to help them deliver their education and training programmes to learners.

For further information, please call our Diploma Line on 0844 576 0028, or visit our website at www.edexcel.com.

If you have any subject specific questions about the content of this Mark Scheme that require the help of a subject specialist, you may find our Ask The Expert email service helpful.

Ask The Expert can be accessed online at the following link:

http://www.edexcel.com/Aboutus/contact-us/

Summer 2010 Publications Code DP023682 All the material in this publication is copyright © Edexcel Ltd 2010

General Marking Guidance

- All candidates must receive the same treatment. Examiners must mark the first candidate in exactly the same way as they mark the last.
- Mark schemes should be applied positively. Candidates must be rewarded for what they have shown they can do rather than penalised for omissions.
- Examiners should mark according to the mark scheme not according to their perception of where the grade boundaries may lie.
- There is no ceiling on achievement. All marks on the mark scheme should be used appropriately.
- All the marks on the mark scheme are designed to be awarded. Examiners should always award full marks if deserved, i.e. if the answer matches the mark scheme. Examiners should also be prepared to award zero marks if the candidate's response is not worthy of credit according to the mark scheme.
- Where some judgement is required, mark schemes will provide the principles by which marks will be awarded and exemplification may be limited.
- When examiners are in doubt regarding the application of the mark scheme to a candidate's response, the team leader must be consulted.
- Crossed out work should be marked UNLESS the candidate has replaced it with an alternative response.

Question	Answer	Mark
Number	74154461	Mark
1(a)	D	(1)
1 (2)	1.5	1 ()
Question Number	Answer	Mark
1(b)	С	(1)
()		
Question Number	Answer	Mark
1(c)	E	(1)
	•	1
Question Number	Answer	Mark
1(d)	В	(1)
()		
Question Number	Answer	Mark
1(e)	D	(1)
	1	1 , ,
Question Number	Answer	Mark
2(a)	D	(1)
Question Number	Answer	Mark
2(b)	С	(1)
Question Number	Answer	Mark
2(c)	С	(1)
Question Number	Answer	Mark
2(d)	В	(1)
Question Number	Answer	Mark
2(e)	D	(1)
Question Number	Answer	Mark
3(a)	D	(1)
Question Number	Answer	Mark
3(b)	В	(1)
	•	
Question Number	Answer	Mark
3(c)	D	(1)

Question	Answer	Mark
Number	Allower	Walk
3(d)	В	(1)
Question Number	Answer	Mark
3(e)	С	(1)
Question Number	Answer	Mark
4	Built up felt - Horizontally	
	Clay tiles - Vertically Mastic asphalt - both	
	Lead - Both	
	Plaster - Not suitable	(5)
		1 \ /
Question Number	Answer	Mark
5(a)	С	(1)
Question Number	Answer	Mark
5(b)	С	(1)
3(3)		(.,
Question	Answer	Mark
Number		
5(c)	В	(1)
Question	Anguer	Mark
Number	Answer	IVIALK
5(d)	D	(1)
Question Number	Answer	Mark
5(e)	D	(1)
- (-)	1-	1 (4)
Question	Answer	Mark
Number		
6	Pitched roof - Timber	
	Floors - Both	
	Walls - Both Drainage - Neither	
	Stairs - Both	(5)
	0.00.0 0.00.0	(♥)
Question	Answer	Mark
Number		
7(a)	E	(1)
Ourant!	American	Ml.
Question Number	Answer	Mark
7(b)	A	(1)
, (v)	<u> ^ </u>	('/

Question	Answer	Mark
Number	C	(1)
7(c)	C	(1)
Question Number	Answer	Mark
7(d)	A	(1)
Question Number	Answer	Mark
7(e)	В	(1)
		1.4
Question Number	Answer	Mark
8(a)	D	(1)
O(u)		(1)
Question Number	Answer	Mark
8(b)	F	(1)
Question Number	Answer	Mark
8(c)	C	(1)
	,	
Question Number	Answer	Mark
8(d)	В	(1)
Question Number	Answer	Mark
8(e)	C	(1)
Question Number	Answer	Mark
9(a)	A	(1)
Question Number	Answer	Mark
9(b)	D	(1)
7(0)	ע ן	\ \ ' <i>\</i>
Question Number	Answer	Mark
9(c)	С	(1)
	•	
Question Number	Answer	Mark
9(d)	E	(1)
Question Number	Answer	Mark
10(a)	F	(1)

Question	Answer	Mark	
Number			
10(b)	В	(1)	
		·	
Question	Answer	Mark	
Number			
10(c)	E	(1)	
Question	Answer	Mark	
Number			
10(d)	C	(1)	
Question	Answer	Mark	
Number			
11	(i) - Both		
	(ii) -Detail B only		
	(iii) -Both		
	(iv) -neither	(4)	
Question		Mark	
Number			
12	 Valuation of variations 		
	 Final Account 		

Question Number	Answer	Mark
13	 Greater thermal mass Sound insulation Noise reduction Less movement Easier to use under-floor heating with Faster construction Uses semi skilled labour for installation Insulation can be laid over the top You can span greater distance Greater load bearing/strength Better resistance to flood damage Provides a working platform during construction Fire resistance Maintenance free Will not rot No chemical treatment Unaffected by vermin No intermediate support required Not affected by weather Improved lifespan potential 	(6)
1	And any other reasonable answer	(6)

Further copies of this publication are available from Edexcel Publications, Adamsway, Mansfield, Notts, NG18 4FN

Telephone 01623 467467 Fax 01623 450481

Email <u>publications@linneydirect.com</u>

Order Code DP023682 Summer 2010

For more information on Edexcel qualifications, please visit www.edexcel.com/quals

Edexcel Limited. Registered in England and Wales no.4496750 Registered Office: One90 High Holborn, London, WC1V 7BH