Code: AE11

Subject: CONTROL ENGINEER

ROLL NO.

AMIETE - ET (OLD SCHEME)

Time: 3 Hours

JUNE 2012

StudentBounty.com PLEASE WRITE YOUR ROLL NO. AT THE SPACE PROVIDED ON EACH PAGE IMMEDIATELY AFTER RECEIVING THE OUESTION PAPER.


NOTE: There are 9 Questions in all.

- Ouestion 1 is compulsory and carries 20 marks. Answer to 0.1 must be written in the space provided for it in the answer book supplied and nowhere else.
- The answer sheet for the O.1 will be collected by the invigilator after 45 minutes of the commencement of the examination.
- Out of the remaining EIGHT Questions answer any FIVE Questions. Each question carries 16 marks.
- Any required data not explicitly given, may be suitably assumed and stated.

Choose the correct or the best alternative in the following: Q.1

 (2×10)

a. The transfer function of the given block diagram is



(A) S^2+5S+3	(B) $S+2/S^2+5S+3$
(C) $1/S^2+6S+5$	(D) $S^3 + 7S^2 + 13S + 6/S + 2$

b. The open loop transfer function of system is G(s) H(s) = $\frac{K(s+2)}{s(s+3)(s+4)}$. Its

centroid is at s =

(A) –2.5	(B) –4
(C) -4.5	(D) 0

- c. The position error coefficient for $G(s) = 100 (s + 2)/s^2$
 - **(A)** 0 **(B)** ∞ (C) 100 **(D)** 2
- d. Using Routh stability criteria, the system having characteristic equation f(s) is s^4 + $8s^3 + 18s^2 + 16s + 5 = 0$ is _____.


(A)	marginal stable	(B)	stable
(C)	unstable	(D)	none of these

www.StudentBounty.com lomework Help & Pastpap

		ROLL NO.	
	The source of supply for synchro	bject: CONTROL ENGINEER	
с.	 (A) an inbuilt source of AC sup (B) an inbuilt source of DC sup (C) an external source of AC su (D) an external source of DC sup 	ply ply ppply	
f.	The laplace transform of unit stee(A) zero(C) 1/s	ep function is (B) one (D) s	
g.	The effect of LEAD compensati	on on the system is	
	(B) It decreases the bandwidth a(C) It decreases the bandwidth a	and makes the speed response slower and makes the speed response faster and makes the speed response slower and makes the speed response faster	
h.	n. Integral error compensation is employed in feedback control systems to		
	(A) improve damping(C) reduce steady state error	(B) improve speed of response(D) increase the bandwidth	
i.	A type -1 plant is changed to type -2 feedback system by the following cascade control action:		
	(A) PD(C) Either PD or PI	(B) PI(D) Neither PD or PI	
j.	j. In a digital control system, selection of a large sampling period		
	 (A) increases the stability margin (B) decreases the stability margin (C) has no effect on stability (D) effects stability depending u 	n	

Answer any FIVE Questions out of EIGHT Questions. Each question carries 16 marks.

- Q.2 a. Explain the reasons for dead-time element in process control loops. Show that dead-time can be represented by the transfer function $e^{St_{D}}$. How do you approximate this transfer function by a rational function? (8)
 - b. Write down the differential equation describing the dynamics of the mechanical system shown in the Fig.2. Draw the electrical equivalent network using force-current analogy. (8)



www.StudentBounty.com Homework Help & Pastpapers





Fig.3

(8)

- b. Explain working of LVDT with neat schematic diagram.
- Q.4 a. Comment on the role of positive feedback and negative feedback in closed –loop control configurations. (6)
 - b. Show with the help of examples that introduction of derivative mode of control in feedback system with proportional control makes the system response less oscillatory. What is its effect on steady- state accuracy? (10)
- Q.5 a. Determine the values of 'K_{mar} and 'P', system is marginally stable and oscillates with frequency 4 rad/sec as shown in Fig.4.
 (8)



b. A unity feedback system is characterized by the open loop transfer function

 $G(s) = \frac{1}{s(0.5s+1)(0.2s+1)} \ .$

- (i) Determine the steady –state errors to unit-step, unit- ramp, and unit parabolic inputs
- (ii) Determine rise time, peak time, peak overshoot, and settling time of the unit –step response of the system. (8)
- **Q.6** a. The open loop transfer function of negative feedback system is given by $G(s)H(s) = \frac{K}{s(s+2)(s^2+2s+5)}; K \ge 0. \text{ Draw the root locus for the system}$ indicating all the points. (8)
 - b. The unity feedback system with open loop transfer function is $G(s) = \frac{K}{1 + 1}$.

www.StudentBounty.com Homework Help & Pastpapers

Code: AE11

Subject: CONTROL ENGINEER

ROLL NO.

(8+8)

Design a lead compensator such that the dominant closed loop poles provide damping ratio of $\zeta = 0.5$ and $\omega_n = 4$ rad/sec.

Roll No.Code: AE11Subject: CONTROL ENGINEERDesign a lead compensator such that the dominant closed loop poles provide
damping ratio of
$$\zeta = 0.5$$
 and $\omega_n = 4$ rad/sec.Q.7 a. Determine the stability of the open loop transfer function
 $G(s)H(s) = \frac{s+1}{s^2(s-2)}$ using Nyquist criteria.

b. Obtain the values of settling time and peak overshoot from the Bode plot of the system having open loop transfer function

$$G(s)H(s) = \frac{0.5e^{-j\omega}}{j\omega(1+j\omega)(1+0.1j\omega)}$$
(8)

Q.8A unity feedback control system has open loop transfer function
$$G(s) = \frac{K}{s(0.1s+1)(0.2s+1)}$$
.The specifications for the system are:(i) $K_v = 30$ (ii) Phase margin $\geq 40^{\circ}$ (iii) Bandwidth = 5 rad/sec.Design a suitable compensation scheme.(16)0.9

- Q.9 note on ar
 - Robust control system. (i)
 - (ii) Advantages of the use of digital computers as compensator device.
 - (iii) Tuning of PID controller.