

# UNIVERSITY OF CAMBRIDGE INTERNATIONAL EXAMINATIONS General Certificate of Education Ordinary Level

METALWORK 6040/02

Paper 2 Practical Test October/November 2008

3 hours

Additional Materials: As listed in the Confidential Instructions

#### **READ THESE INSTRUCTIONS FIRST**

Please see page 2.

All dimensions are in millimetres unless stated otherwise.



From the materials supplied you are to make the LEVER AND BRACKET shown in the drawings.

All dimensions are in millimetres.

The following materials are supplied:

- Part 1 One piece BDMS  $20 \times 5 \times 162$  long. Both ends sawn.
- Part 2 One piece MS sheet  $52 \times 2 \times 62$  long. One end and one edge square.
- Part 3 One piece BDMS  $20 \times 3 \times 52$  long. One end square.
- Part 4 One piece BDMS  $\emptyset8 \times 26$  long. Prepared prior to the examination.
- Part 5 One piece BDMS  $20 \times 5 \times 35$  long. Both ends square.
- Part 6 One piece BDMS  $10 \times 10 \times 30$  long. Both ends square.
- Part 7 Two pieces BDMS  $\emptyset8 \times 6$  long. Prepared prior to the examination.

Two  $\emptyset$ 3 × 15 long round head steel rivets.

One M6  $\times$  12 long cheese head or round head screw.

One M6 × 15 long cheese head or round head screw and locknut.

One M6 × 20 long cheese head or round head screw and locknut.

(Two standard nuts can be used for each screw if locknuts are not available.)

One bag in which to enclose the work.

Two tie-on labels.

#### **Notes**

### **Working Procedures**

- A Part 4 should be silver soldered to Part 1 and the back filed flat.
- B Part 3 should be riveted to Part 2, using the round head rivets supplied, with the two spacers Part 7 between them.
- C Part 5 should be fixed to Part 1 using the M6  $\times$  12 long screw provided.
- D Part 1 should be fixed to Part 2 using the M6  $\times$  15 long screw and locknut supplied.
- E Part 6 should be shaped at both ends to remove the sharp corners.
- F Part 6 should be fixed to Part 1 using the M6 × 20 long screw and locknut supplied.

© UCLES 2008 6040/02/O/N/08

#### **General Notes**

- A second supply of material is **not** allowed. If you make a mistake, do your best to work as near to the dimensions given in the drawing as possible.
- Any dimensions omitted are left to your discretion.
- Attempt to complete the work but remember that a partly completed piece of work of good quality may gain more marks than one which is complete but inaccurate or poorly finished.
- Clean up all parts by draw filing. Emery cloth or similar must not be used.
- Write your name and examination number on both labels supplied, attach one to your work and
  the other to the bag in which your work is enclosed. Put all worked and unworked materials into the
  bag, with the exception of waste.

© UCLES 2008 6040/02/O/N/08

## **BLANK PAGE**

Permission to reproduce items where third-party owned material protected by copyright is included has been sought and cleared where possible. Every reasonable effort has been made by the publisher (UCLES) to trace copyright holders, but if any items requiring clearance have unwittingly been included the publisher will be pleased to make amends at the earliest possible opportunity.

University of Cambridge International Examinations is part of the Cambridge Assessment Group. Cambridge Assessment is the brand name of University of Cambridge Local Examinations Syndicate (UCLES), which is itself a department of the University of Cambridge.